



Paul Smith's College Open Work Order List

Printed: 4/30/2012 5:08:20 AM

Report Criteria

Target Date is less than **4/30/2012**

Type is **Corrective Maintenance, Follow-Up, Miscellaneous Time Type** or **Scheduled**

Status is **Issued, On-Hold** or **Requested**

Building	Work Order #	Reason	Parent Location	Asset Name	Issued	Target Date	Status
Administration Building							
Administration Building	23701	Please paint 103 and 103A office over summer break.	1st Floor	Office 103	3/6/2012	3/9/2012	ONHOLD
Administration Building	342	Please look at Karen Potts' window, it's very hard for her to open.	1st Floor	Office 110	3/21/2012 5:43:17 AM	3/24/2012	ISSUED
Administration Building	434	Open junction boxes and open wiring splices present. Basement electrical room: R wall conduit from light.	Bldg Ext	Elect Room	3/27/2012 6:08:00 AM	3/30/2012	ISSUED
Administration Building	23817	Would you please bring us two more bottles of water? Thank you.	2nd Floor	Office 211	3/30/2012 7:05:36 AM	4/2/2012	ISSUED
Administration Building	24232	Other - The water in the sink is cold most of the time - no hot water.	2nd Floor	Restroom Women By 209	4/19/2012 12:01:22 PM	4/22/2012	ISSUED
Administration Building	24254	Please put in screen...done just needed paper trail	Paul Smiths College	Administration Building	4/20/2012 1:20:00 PM	4/23/2012	ISSUED
Administration Building	24271	Roof leak over bathroom.	2nd Floor	Restroom By 205	4/24/2012 5:27:09 AM	4/27/2012	ISSUED
Administration Building - 7 Total:							

Alumni Hall

Alumni Hall	441	Clothes dryer exhaust systems shall be...exhausted in accordance with manufacturer's instructions. Laundry: evaluate exhaust duct installation.	1st Floor	Laundry Room	3/27/2012 9:24:00 AM	3/30/2012	ISSUED
Alumni Hall	442	Carbon monoxide alarms shall be provided on every story which contains a carbon monoxide source. CO alarms required- review amended code sections. Take temporary ones out of Upper and Lower hallways.	Paul Smiths College	Alumni Hall	3/27/2012 9:51:00 AM	3/30/2012	ISSUED

Alumni Hall	24150	It looks like someone smashed the automatic light switch.	1st Floor	Lounge	4/12/2012 5:25:43 AM	4/14/2012	ISSUED
Alumni Hall - 3 Total:							
Blum House							
Blum House	22006	the screen in the window is the wrong size, please replace with the right one (spares are in the basement)	1st Floor	Students Room 103	11/3/2011	11/8/2011	ISSUED
Blum House - 1 Total:							
Buxton Annex							
Buxton Annex	24177	build shelving in club storage in the Buxton Annex please have done by graduation	Buxton Annex	1st Floor	4/16/2012 5:34:00 AM	4/19/2012	ISSUED
Buxton Annex - 1 Total:							
Campus Grounds							
Campus Grounds	24220	Please bring 2 small truck loads of mulch to Goulds Garden before the 27th.	Paul Smiths College	Campus Grounds	4/18/2012 8:48:00 AM	4/21/2012	ISSUED
Campus Grounds - 1 Total:							
Campus Wide							
Campus Wide	24244	Please refurbish front entrance signs.	Campus Wide	Campus Wide	4/20/2012 7:23:39 AM	4/23/2012	ISSUED
Campus Wide	24282	make keys for conferance services summer rentals.	Paul Smiths College	Campus Wide	4/25/2012 9:38:00 AM	4/28/2012	ISSUED
Campus Wide - 2 Total:							
Cantwell Hall							
Cantwell Hall	20598	101-computer lab- needs the window wall painted please	1st Floor	Computer Hub 101	8/31/2011	9/6/2011	ISSUED
Cantwell Hall	21631	please paint all the door frames in cantwell. if at all possible before open house.	Paul Smiths College	Cantwell Hall	10/6/2011	10/11/2011	ONHOLD
Cantwell Hall	23577	Petroleum storage tank - Water 10" something	Paul Smiths College	Cantwell Hall	2/27/2012	3/1/2012	ISSUED
Cantwell Hall	23621	The light above the Ganzi sign on the outside of the front of the building is hanging off the building.	Paul Smiths College	Cantwell Hall	2/28/2012	3/2/2012	ISSUED
Cantwell Hall	23665	The rack oven that the repair man came to look at last week is not working again. He sprayed it but that did not do the job. The rack will not move at all and is stuck inside the oven.	1st Floor	Baking Lab 103	3/5/2012	3/8/2012	ISSUED
Cantwell Hall	464	#1. Open junction boxes, open wiring-Boiler room above the door	Bldg Ext	Mech Rm Boiler	3/27/2012 12:27:00 PM	3/30/2012	ISSUED

Cantwell Hall	471	#4 Approved covers shall be provided for all switch and outlet boxes-104: cover for outlet being coffee grinder	Bldg Ext	Mech Rm Boiler	3/27/2012 12:42:00 PM	3/30/2012	ISSUED
Cantwell Hall	474	#6 Electrical wiring, devises, etc modified or damaged or constitutes an electrical shock hazard-102: wiring suspended from ceiling tied in knots	Bldg Ext	Mech Rm Boiler	3/27/2012 1:04:10 PM	3/30/2012	ISSUED
Cantwell Hall	476	#8 Required working space and clearance not maintained in fron of electrical service-107: storage shelves in front of panel	Bldg Ext	Mech Rm Boiler	3/27/2012 1:18:00 PM	3/30/2012	ISSUED
Cantwell Hall	477	#10 Commercial cooking systems not maintained 211: nozzles not properly aligned	Bldg Ext	Mech Rm Boiler	3/27/2012 1:22:40 PM	3/30/2012	ISSUED
Cantwell Hall	478	#11 Commercial cooking systems not maintained 210: nozzles not properly aligned	Bldg Ext	Mech Rm Boiler	3/27/2012 1:24:35 PM	3/30/2012	ISSUED
Cantwell Hall	482	#12 Swinging fire doors do not close formt eh full-open position and latch automatically Kitchens/corridor door propped or not closing	Paul Smiths College	Cantwell Hall	3/28/2012 6:37:13 AM	3/31/2012	ISSUED
Cantwell Hall - 12 Total:							

Clinton Hall

Clinton Hall	487	#4 Electrical wiring, devices, etc. modified or damaged or constitutes an electrical shock hazard. Floor #1 Laundry room GFCI sabove folding table.	1st Floor	Laundry Room	3/28/2012 8:34:00 AM	3/31/2012	ISSUED
Clinton Hall	489	#6 multiplug adaptors, such as cube adaptors, unfused plug strips...shall be prohibited. 108: Lwall by entry, unfused triple tap	1st Floor	Students Room 108	3/28/2012 8:41:48 AM	3/31/2012	ISSUED
Clinton Hall	490	#7 Clothes dryer exhaust systems shall be...exhausted in accordance with manufacturers instructions. Laundry: evaluate exhaust duct installation.	Paul Smiths College	Clinton Hall	3/28/2012 8:47:13 AM	3/31/2012	ISSUED
Clinton Hall - 3 Total:							

Currier Hall

Currier Hall	22002	The window screen is missing from the window.	1st Floor	Laundry Rm	11/3/2011	11/8/2011	ISSUED
Currier Hall	22893	The main door has splintered in the back and the interior of the door is falling out.	1st Floor	Students Room 125	1/25/2012	1/30/2012	ONHOLD
Currier Hall	23572	Petroleum storage tank - tag missing.	Paul Smiths College	Currier Hall	2/27/2012	3/1/2012	ISSUED
Currier Hall	325	Other There are no paper towels in the dispenser.	1st Floor	Bathroom Women By 120	3/20/2012 12:14:30 PM	3/22/2012	ISSUED
Currier Hall	413	Bathroom off far stairwell both toilet paper dispensers are missing covers.	2nd Floor	Bathroom Women By 226	3/26/2012 10:17:00 AM	3/29/2012	ISSUED
Currier Hall	495	#3 Extension cord used to supply more than one appliance. 105: R side, Extension cord with unfused triple tap.	1st Floor	Students Room 105	3/28/2012 9:10:31 AM	3/31/2012	ISSUED

Currier Hall	500	#7 Clothes dryer exhaust systems shall be... exhausted in accordance with manufacturers instructions. Laundry: evaluate exhaust duct installations.	Paul Smiths College	Currier Hall	3/28/2012 9:55:26 AM	3/31/2012	ISSUED
Currier Hall	24022	I've been told that the women's bathroom has become really dirty and unsanitary. The female resident's would appreciate it if the bathroom would be cleaned up as soon as possible.	1st Floor	Bathroom Men By 123	4/3/2012 5:06:49 AM	4/5/2012	ISSUED
Currier Hall	24289	Other, white mold on carpet, broken dresser drawers	2nd Floor	Students Room 204	4/26/2012 10:37:26 AM	4/29/2012	ISSUED
Currier Hall	24299	The window screen has been torn open and the residents are concerned that it will be ripped even more.	1st Floor	Students Room 101	4/27/2012 5:08:13 AM	4/29/2012	ISSUED
Currier Hall - 10 Total:							

Facilities Building

Facilities Building	375	behind facilities the access door for the Chimney fell off. please clean and put back on.	Facilities Building	Building Exterior	3/22/2012 9:54:00 AM	3/25/2012	ONHOLD
Facilities Building	23804	#2 Fire extinguisher improperly selected installed or maintained-Wood shop: record date as month/Day/Year	Paul Smiths College	Facilities Building	3/29/2012 12:37:00 PM	4/1/2012	ISSUED
Facilities Building	23806	#4 Automotive motor fuel-dispensing facilities not in accordance with chapter 22....Fuel-dispensing site to be evaluated in detail	Paul Smiths College	Facilities Building	3/29/2012 12:48:00 PM	4/1/2012	ISSUED
Facilities Building	24283	Please spray the hinges on Tony's office door with WD40 or something so that it does not creak. Thank you!	Facilities Mgmnt	Office Tony	4/25/2012 1:03:00 PM	4/28/2012	ISSUED
Facilities Building - 4 Total:							

Faculty 6

Faculty 6	23592	I want a third light installed in the ceiling of the covered porch in front of the house.	Paul Smiths College	Faculty 6	2/23/2012	2/28/2012	ISSUED
Faculty 6 - 1 Total:							

Faculty 7

Faculty 7	427	Front porch and stairs need painting due to weathering.	Paul Smiths College	Faculty 7	3/27/2012 5:14:52 AM	3/30/2012	ISSUED
Faculty 7 - 1 Total:							

Franklin Hall

Franklin Hall	23437	Petroleum storage tank - label peeling	Paul Smiths College	Franklin Hall	2/27/2012	3/1/2012	ISSUED
Franklin Hall	378	My shower only produces hot water when the faucet is on. If you could fix that, it would be greatly appreciated!	1st Floor	Students Room 101	3/23/2012 5:21:52 AM	3/26/2012	ISSUED
Franklin Hall	418	Makes a really loud noise after flushing. Please fix!	1st Floor	Students Room 105	3/26/2012 12:19:00 PM	3/29/2012	ISSUED

Franklin Hall	23815	#8 Clothes dryer exhaust system shall be ...exhausted in accordance with manufacturer's instructions Laundry: evaluate exhaust duct installation	Paul Smiths College	Franklin Hall	3/29/2012 1:33:00 PM	4/1/2012	ISSUED
Franklin Hall	24097	EXIT DOOR FACING ESSEX WILL NOT LATCH AND IS RUBBING ON THE DOOR JAMB.	Bldg Ext	Building Exterior	4/4/2012 8:55:00 AM	4/5/2012	ISSUED
Franklin Hall - 5 Total:							

Freer Hall

Freer Hall	23664	A temporary fix was done for the leaking ceiling please do appropriate repair to roof when weather permits.	2nd Floor	Classroom 209	3/5/2012	3/8/2012	ISSUED
Freer Hall	23825	#5 Electrical wiring devices etc, modified or damaged or constitutes an electricalshock hazard-109: Panel on right, bottom needs new cover	1st Floor	Research Faculty 109	3/30/2012 12:02:09 PM	4/2/2012	ISSUED
Freer Hall	24028	Light switch panel bottom row, switch to the far right has a short in it	1st Floor	Auditorium 113	4/3/2012 5:58:45 AM	4/6/2012	ISSUED
Freer Hall	24153	There is a concrete step at the main entrance of Freer that is broken and the steel is showing through. This is a safety issue which needs to be addressed immediately.	Paul Smiths College	Freer Hall	4/12/2012 9:51:35 AM	4/15/2012	ISSUED
Freer Hall	24185	Starting to Spring clean. There is a cart full of large items for the trash to be removed.	1st Floor	Prep Room 101-102 101a	4/16/2012 10:33:14 AM	4/19/2012	ISSUED
Freer Hall	24187	replace pencil sharpener. new one on bench next to door.	1st Floor	Lab 101	4/16/2012 10:49:00 AM	4/19/2012	ISSUED
Freer Hall	24188	install pencil sharpener. Box is on bench next to door. Where ever there is room on the wall is fine	1st Floor	Lab 110	4/16/2012 10:47:00 AM	4/19/2012	ISSUED
Freer Hall	24280	Key pad on door handle is broken. Please remove and replace with regular lock and key.	1st Floor	Prep Room 118a	4/25/2012 1:00:00 PM	4/28/2012	ISSUED
Freer Hall - 8 Total:							

Hillside Hall

Hillside Hall	21845	6 of the 7 windows at the front entrance/common area were missing window screens.	Hillside Hall	1st Floor	10/27/2011	11/1/2011	ONHOLD
Hillside Hall	23574	Petroleum storage tank - water indication bulb out.	Paul Smiths College	Hillside Hall	2/27/2012	3/1/2012	ISSUED
Hillside Hall	23835	#7 Smoking shall not be permitted, nor shall a person smoke, throw or deposit any lighted or....212: smoking in student room- additional remarks attached	2nd Floor	Students Room 212	3/30/2012 12:29:02 PM	4/2/2012	ISSUED
Hillside Hall	24145	Please fix toilet	2nd Floor	Students Room 202	4/11/2012 9:13:00 AM	4/14/2012	ISSUED
Hillside Hall	24146	Please fix toilet	2nd Floor	Students Room 203	4/11/2012 9:14:00 AM	4/14/2012	ISSUED

Hillside Hall	24147	Please fix toilet	2nd Floor	Students Room 205	4/11/2012 9:15:00 AM	4/14/2012	ISSUED
Hillside Hall	24287	The Hillside exterior door closest to Lower St. Regis needs it door closer re-adjusted. The door does not close normally and latch properly.	Hillside Hall	Bldg Ext	4/26/2012 8:29:00 AM	4/29/2012	ISSUED
Hillside Hall - 7 Total:							

Inner Sanctum

Inner Sanctum	23836	#1 Electrical wiring, devices, etc modified or damaged or constitutes an electrical shock hazard; Lower garage door, outlet below electrical panel	Paul Smiths College	Inner Sanctum	3/30/2012 12:32:13 PM	4/2/2012	ISSUED
Inner Sanctum	23837	#2 Doors into electrical control panel rooms and each disconnect shall be labeled...Lower garage door, electrical panel directory	Paul Smiths College	Inner Sanctum	3/30/2012 12:34:00 PM	4/2/2012	ISSUED
Inner Sanctum - 2 Total:							

Joan Weill Adirondack Library

Joan Weill Adirondack Library	23481	please reappear the crack that is in the wall-crack runs from ceiling to the floor.	1st Floor	It Help Desk 112	2/14/2012	2/17/2012	ISSUED
Joan Weill Adirondack Library	23482	please paint the entire office.	1st Floor	It Help Desk 112	2/14/2012	2/17/2012	ONHOLD
Joan Weill Adirondack Library	290	Computer Lab- Back wall needs painting all marked up.	2nd Floor	Seminar Room 206	3/16/2012 9:58:00 AM	3/26/2012	ISSUED
Joan Weill Adirondack Library	23838	#1 Fire protection system not inspected, tested, or maintained per refrence standard...Main entrance: painted, missing sprinkler covers	1st Floor	Foyer Main Entrance	3/30/2012 12:36:00 PM	4/2/2012	ISSUED
Joan Weill Adirondack Library	23840	#2 Fire protection system not inspected, tested, or maintained poer refrence standard....Sprinkler control room: Sprinkler wrenches	Joan Weill Adirondack Library	1st Floor	3/30/2012 12:56:00 PM	4/2/2012	ISSUED
Joan Weill Adirondack Library	23946	#8 Means of egress is obstructed and not readily available for use. Adirondack room: exit by kitchen plants	2nd Floor	Adirondack Room 201	4/2/2012 6:47:03 AM	4/5/2012	ISSUED
Joan Weill Adirondack Library	23947	#9 Fire protection system not inspected, tested, or maintained per refrence standard Server IT room; concealed sprinkler coverplates	1st Floor	Server Room 113	4/2/2012 6:57:22 AM	4/5/2012	ISSUED
Joan Weill Adirondack Library	23948	#10 Flire department connections shall be installed in accordance with the NFPA standard Signange access need evaluation	Paul Smiths College	Joan Weill Adirondack Library	4/2/2012 6:59:24 AM	4/5/2012	ISSUED
Joan Weill	23949	#11 Occupancy load not posted Review occupant load and	Paul Smiths	Joan Weill	4/2/2012	4/5/2012	ISSUED

Adirondack Library		egress capacity	College	Adirondack Library	7:03:10 AM		
Joan Weill Adirondack Library	24119	Heat not turning off- some areas are pushing 80 degrees	Paul Smiths College	Joan Weill Adirondack Library	4/9/2012 11:37:23 AM	4/12/2012	ISSUED
Joan Weill Adirondack Library	24207	Cut access panel to tighten and install new bolts in beams	Paul Smiths College	Joan Weill Adirondack Library	4/17/2012 10:59:32 AM	4/20/2012	ISSUED
Joan Weill Adirondack Library	24256	PLease replace window hardware in crank out window label over lock "please do not open" For Joey	2nd Floor	Group Study 205	4/20/2012 1:18:00 PM	4/23/2012	ISSUED
Joan Weill Adirondack Library	24261	Lights are not working in library air handler room between air handlers	1st Floor	Mech Rm 116	4/23/2012 8:43:27 AM	4/26/2012	ISSUED
Joan Weill Adirondack Library	24263	Fix leaking custodial mop sink faucet in library	1st Floor	Janitor Closet 114	4/23/2012 8:51:35 AM	4/26/2012	ISSUED
Joan Weill Adirondack Library	24264	Ceiling tiles need to be put back into place.	2nd Floor	Group Study 210	4/23/2012 8:53:29 AM	4/26/2012	ISSUED
Joan Weill Adirondack Library	24277	Stone wall next to the ramp at library loading dock needs to be remorteted.	Bldg Ext	Building Exterior	4/25/2012 7:53:00 AM	4/28/2012	ISSUED
Joan Weill Adirondack Library	24279	Ice tape is hanging out of gutter over main entrance to the library	Paul Smiths College	Joan Weill Adirondack Library	4/25/2012 11:34:29 AM	4/28/2012	ISSUED
Joan Weill Adirondack Library	24281	slow down door closures library foyer.	Joan Weill Adirondack Library	Bldg Ext	4/25/2012 9:35:00 AM	4/28/2012	ISSUED
Joan Weill Adirondack Library	24285	Other - Front door slams all the time. Might be time for a new closer.	1st Floor	Foyer Main Entrance	4/26/2012 8:31:00 AM	4/29/2012	ISSUED
Joan Weill Adirondack Library	24288	Hand rail junction on the library main staircase has separated, should be reglued and nailed.	1st Floor	Stairwell Main Front	4/26/2012 8:59:01 AM	4/29/2012	ISSUED
Joan Weill Adirondack Library	24294	Can we have an extra pad lock put on our Pepsi cooler in the Hutch. Thanks	Joan Weill Adirondack Library	1st Floor	4/26/2012 12:13:03 PM	4/29/2012	ISSUED
Joan Weill Adirondack Library	24295	Event Set-up/Tear-down Please deliver 2 gas grills with tank to outside the Library for TRIO BBQ before 12pm and pick up after 3pm	Paul Smiths College	Joan Weill Adirondack Library	4/26/2012 1:11:01 PM	4/29/2012	ISSUED
Joan Weill	24297	Could we have pepsi called in to fix the vending machine.	1st Floor	Hutchins Study	4/26/2012	4/29/2012	ISSUED

Adirondack Library		There are bottles stuck and it won't vend. Thanks		Cafe 100	2:42:33 PM		
Joan Weill Adirondack Library - 23 Total:							

Joan Weill Student Center

Joan Weill Student Center	22769	Student center boiler room near nurses office has a leak in the heating supply line in the room with the fuel oil day tank and fuel oil pumps. Just dripping for now but should be looked into before it becomes something bigger.	Joan Weill Student Center	1st Floor	1/16/2012	1/18/2012	ONHOLD
Joan Weill Student Center	294	Outside of the bookstore there used to be a commemorative plaque that said "In Honor of the Kirche Family". It is currently missing. Please order a replacement and install.	Ground Floor	Hallway	3/19/2012 5:37:00 AM	3/22/2012	ISSUED
Joan Weill Student Center	313	Pick up a spring board flooring at the LPCA annex and bring it to the pine room before noon on may 3rd. Disassemble on may 7th and have back to LPCA by 2:30	1st Floor	Pine Room 102	3/19/2012 9:28:09 AM	3/22/2012	ISSUED
Joan Weill Student Center	394	Fryers are kicking on and off again..Thanks	1st Floor	Lakeside Dining Hall 105	3/26/2012 5:19:31 AM	3/27/2012	ISSUED
Joan Weill Student Center	437	Mechanical Repair Top right oven not working, also fryers keep shutting off during use. Coul we get a truck for an inner sanctum drop off? Today maybe?	1st Floor	Kitchen	3/27/2012 6:39:39 AM	3/30/2012	ISSUED
Joan Weill Student Center	23956	#6 Storage of combustible materials shall be maintained 18" below ceiling of sprinklered area: prep kitchen shelving storage	1st Floor	Lakeside Dining Hall 105	4/2/2012 8:43:40 AM	4/5/2012	ISSUED
Joan Weill Student Center	23959	#9 Curtains draperies, hangings & other decorative materials on ceilings & walls not flame resistant curtains on stage in bobcat theater	2nd Floor	Bobcat Cafe 201	4/2/2012 9:25:46 AM	4/5/2012	ISSUED
Joan Weill Student Center	24088	Back stairwell pine room level water damage on ceiling by rock wall and by windows. Also wall and ceiling is cracked.	Joan Weill Student Center	1st Floor	4/4/2012 5:28:57 AM	4/7/2012	ISSUED
Joan Weill Student Center	24093	We need knobs for the grill in the kitchen and the pizza station needs new knobs	Joan Weill Student Center	2nd Floor	4/4/2012 8:37:39 AM	4/7/2012	ISSUED
Joan Weill Student Center	24110	Mechanical Repair Mixer ON button will not stay engaged	Paul Smiths College	Joan Weill Student Center	4/9/2012 5:07:29 AM	4/9/2012	ISSUED
Joan Weill Student Center	24120	Exam room floors need to be stripped, sealed, and waxed.	Ground Floor	Nurses Station 003g	4/9/2012 11:47:27 AM	4/12/2012	ISSUED
Joan Weill Student Center	24154	The thermostat has been ripped off the wall and is missing.	1st Floor	Restroom Men	4/12/2012 10:02:14 AM	4/15/2012	ISSUED
Joan Weill Student Center	24162	heat in the ladies room on the main floor and and also the hallway that leads to the communter lounge is very warm	Paul Smiths College	Joan Weill Student Center	4/13/2012 7:25:12 AM	4/16/2012	ISSUED

Joan Weill Student Center	24203	Clean all flies out of light fixtures in dining hall and lobby before May 4th.	1st Floor	Lakeside Dining Hall 105	4/17/2012 10:11:00 AM	4/20/2012	ISSUED
Joan Weill Student Center	24201	Repair wall in corner of stairwell leaving St. Regis cafe towards Pine room.	Joan Weill Student Center	1st Floor	4/17/2012 9:54:37 AM	4/20/2012	ISSUED
Joan Weill Student Center	24202	Repair wall in corner of stairwell leading to Bobcat	1st Floor	Stairwell Bobcat Cafe	4/17/2012 9:58:56 AM	4/20/2012	ISSUED
Joan Weill Student Center	24206	Entrance closest to Lakeside dorm replace broken/missing tile.	Joan Weill Student Center	Bldg Ext	4/17/2012 10:31:33 AM	4/20/2012	ISSUED
Joan Weill Student Center	24265	Repair wall and maybe replace whatever sign was ripped off the wall at the entrance to the south east boiler room	Ground Floor	Mech Rm Boiler 018	4/23/2012 8:56:00 AM	4/26/2012	ISSUED
Joan Weill Student Center	24296	We have a cluster of bugs in one corner of the Large Windows in Lakeside. Don't know if they are from outside or coming in from the wall. Thanks	1st Floor	Lakeside Dining Hall 105	4/26/2012 2:42:02 PM	4/29/2012	ISSUED
Joan Weill Student Center - 19 Total:							

Lakeside Hall

Lakeside Hall	23565	There are 5 fist sized holes in the Hallway walls	1st Floor	Hallway	2/27/2012	3/1/2012	ISSUED
Lakeside Hall	23575	Petroleum storage tank - no buzzer	Paul Smiths College	Lakeside Hall	2/27/2012	3/1/2012	ISSUED
Lakeside Hall	23963	#2 cooking appliances not permitted in rooming or dormitory unti...208: sandwich maker on left	2nd Floor	Students Room 208	4/2/2012 9:40:39 AM	4/5/2012	ISSUED
Lakeside Hall	23964	#3 Multiple adapters such as cube adapters unfused plug strips, shall be prohibited-208: unfused green triple tap at entrance	2nd Floor	Students Room 208	4/2/2012 9:44:02 AM	4/5/2012	ISSUED
Lakeside Hall	23966	#5 Electrical wiring devices, etc, modified or damaged or constitutes an electrical shock hazard..205: Damaged cord on Refrigerator	2nd Floor	Students Room 205	4/2/2012 9:48:29 AM	4/5/2012	ISSUED
Lakeside Hall	23977	Holes in the wall, right side.	1st Floor	Hallway	4/2/2012 10:49:00 AM	4/5/2012	ISSUED
Lakeside Hall	24105	Carpentry- The screen door going into the lakeside apt needs the hinges repaired and the actual screen fixed as well. Thank you!	Lakeside Hall	Bldg Ext	4/6/2012 9:21:00 AM	4/9/2012	ISSUED
Lakeside Hall - 7 Total:							

Lambert Hall

Lambert Hall	23438	Petroleum storage tank - tag peeling.	Paul Smiths College	Lambert Hall	2/27/2012	3/1/2012	ISSUED
Lambert Hall - 1 Total:							

Livermore Hall

Livermore Hall	370	The resident would like his carpet steam cleaned. From the bed to the right side of the room.	1st Floor	Students Room 107	3/22/2012 5:57:03 AM	3/25/2012	ISSUED
Livermore Hall	23985	#7 Relocatable power taps shall be directly connected to a permanently installed receptacle-222:Power tap into extension cord by window	2nd Floor	Students Room 222	4/2/2012 11:15:00 AM	4/5/2012	ISSUED
Livermore Hall	23971	#1 Open junction boxes and open wiring splices present-Boiler room: rear wall, tray over switches	Bldg Ext	Mech Rm Boiler	4/2/2012 10:18:18 AM	4/5/2012	ISSUED
Livermore Hall	23972	#2 Doors into electrical control panel rooms and each disconnect shall be labeled....Basement electric panel next to FACP, Directory	Bldg Ext	Mech Rm Boiler	4/2/2012 10:21:47 AM	4/5/2012	ISSUED
Livermore Hall	23979	#4 Required fire resistance rating of walls, shafts, or floors not maintained...Basement stairwell Door: Hole above handle	Basement	Basement	4/2/2012 10:52:42 AM	4/5/2012	ISSUED
Livermore Hall	23984	#6 Curtains, draperies, hangings & other decorative materials on ceilings & walls not flame resistant-226: door covered in post-it notes	2nd Floor	Students Room 226	4/2/2012 11:12:30 AM	4/5/2012	ISSUED
Livermore Hall	23986	#8 Extension cord used to supply more than one appliance: 222: extension cord for multiple appliances, window	2nd Floor	Students Room 222	4/2/2012 11:17:16 AM	4/5/2012	ISSUED
Livermore Hall	23989	#11 The installation of nonportable fuel gas appliances shall comply with the fuel gas code....Propane water heater fuel supply installation	Paul Smiths College	Livermore Hall	4/2/2012 11:27:25 AM	4/5/2012	ISSUED
Livermore Hall	24115	Downstairs men room left GFI inoperative	1st Floor	Bathroom Men By Laundry	4/9/2012 11:08:37 AM	4/12/2012	ISSUED
Livermore Hall	24116	Left GFI inoperative.	1st Floor	Bathroom Women By 103	4/9/2012 11:11:32 AM	4/12/2012	ISSUED
Livermore Hall	24117	Left GFI inoperative	2nd Floor	Bathroom Women By 203	4/9/2012 11:24:31 AM	4/12/2012	ISSUED
Livermore Hall	24118	Long junction box cover is missing, a lot of wiring is exposed.	Bldg Ext	Mech Rm Boiler	4/9/2012 11:28:22 AM	4/12/2012	ISSUED
Livermore Hall	24129	Heat won't shut off	1st Floor	Students Room 121	4/10/2012 5:06:01 AM	4/12/2012	ISSUED
Livermore Hall	24239	shade in the lounge is broken	1st Floor	Lounge 118	4/19/2012 1:17:50 PM	4/22/2012	ISSUED
Livermore Hall	24270	Broken window due to vandalism.	1st Floor	Students Room 102	4/24/2012 5:19:00 AM	4/27/2012	ISSUED
Livermore Hall	24273	please put wood blocks on the windows of Livermore over the roof of the break room to only allow the windows to open 6"	Livermore Hall	2nd Floor	4/24/2012 7:37:52 AM	4/27/2012	ISSUED
Livermore Hall	24284	Screen was stolen, request replacement please.	1st Floor	Students Room 113	4/26/2012 8:25:41 AM	4/29/2012	ISSUED

<i>Livermore Hall - 17 Total:</i>							
Lms Hall							
Lms Hall	416	Middle stall broken toilet paper dispenser.	2nd Floor	Restroom Men	3/26/2012 11:02:09 AM	3/29/2012	ISSUED
Lms Hall	23796	Please take down the vents in both men's bathrooms and paint.	Paul Smiths College	Lms Hall	3/29/2012 11:00:58 AM	4/1/2012	ISSUED
Lms Hall	23797	Directly behind the door the tile is broken. Please replace.	1st Floor	Bathroom Men	3/29/2012 11:09:38 AM	4/1/2012	ISSUED
Lms Hall	23995	#5 Relocatable power taps shall be directly connected to a permanently installed receptacle-220: Daisy chained power taps on R	2nd Floor	Students Room 220	4/2/2012 11:44:37 AM	4/5/2012	ISSUED
Lms Hall	23996	#6 Electrical equipment, wiring, appliances not installed and maintained in safe and approved-215: Decorative lights against paper & around bed	2nd Floor	Students Room 215	4/2/2012 11:47:36 AM	4/5/2012	ISSUED
Lms Hall	23997	#7 Relocatable power taps shall be directly connected to a permanently installed receptacle-204: Daisy chained power taps on L	2nd Floor	Students Room 204	4/2/2012 11:49:28 AM	4/5/2012	ISSUED
Lms Hall	23998	#8 Electrical equipment, wiring, appliances not installed and maintained in safe and approved-204: Flat screen TV duct taped to bed frame	2nd Floor	Students Room 204	4/2/2012 12:03:07 PM	4/5/2012	ISSUED
Lms Hall	24000	#10 Building shall have approved address numbers plainly legible that contrast with background	Paul Smiths College	Lms Hall	4/2/2012 12:14:00 PM	4/5/2012	ISSUED
Lms Hall	24087	The breaker keeps tripping.	Lms Hall	1st Floor	4/4/2012 5:20:29 AM	4/7/2012	ISSUED
Lms Hall	24246	Can I get the soap dispenser changed. The one near the garbage can.	2nd Floor	Restroom Men	4/20/2012 7:41:02 AM	4/23/2012	ISSUED
<i>Lms Hall - 10 Total:</i>							

Lower St Regis

Lower St Regis	383	hallway near room 117 carpet is wet possible shower leak.	Lower St Regis	1st Floor	3/23/2012 8:47:58 AM	3/26/2012	ISSUED
Lower St Regis	385	tile needs to be put back in place	1st Floor	Mechanical Room 101	3/23/2012 9:05:17 AM	3/26/2012	ISSUED
Lower St Regis	23790	Needs a new stove handle.	1st Floor	Main Room 109	3/29/2012 5:19:00 AM	4/1/2012	ISSUED
Lower St Regis	24001	#1 Fire protection system not inspected tested, or maintained per refrence standard-sprinkler control room: inadequate spares/wrenches	Paul Smiths College	Lower St Regis	4/2/2012 12:17:46 PM	4/5/2012	ISSUED
Lower St Regis	24004	#4 Means of egress is obstructed and not readily available for use 203:Entire area disorderly/corridor storage	2nd Floor	Main Room 203	4/2/2012 12:51:58 PM	4/5/2012	ISSUED

Lower St Regis	24127	shower door is about to come off of its hinges and needs to be replaced	2nd Floor	Bedroom 213c	4/10/2012 5:28:00 AM	4/12/2012	ISSUED
Lower St Regis	24290	missing screen in bedroom 205b	2nd Floor	Bedroom 205b	4/26/2012 10:39:16 AM	4/29/2012	ISSUED
Lower St Regis	24291	Missing screens in main room along with all bedrooms	1st Floor	Mainroom 113	4/26/2012 10:40:29 AM	4/29/2012	ISSUED
Lower St Regis	24292	Missing screens in main room and also in all of the personal bedrooms	1st Floor	Main Room 109	4/26/2012 10:41:02 AM	4/29/2012	ISSUED
Lower St Regis - 9 Total:							

Overlook

Overlook	503	Freezer isn't freezing. Vents are not blocked and things closest to vent are not freezing.	Second Floor	Kitchen/living Area 214	3/28/2012 12:01:39 PM	3/31/2012	ISSUED
Overlook	24013	#8 Combustible material stored in boiler, mechanical, or electrical room-214: Storage in mechanical room	Second Floor	Mechanical Room 2143	4/2/2012 1:14:36 PM	4/5/2012	ISSUED
Overlook	24014	#9 Means of egress is obstructed and not readily available for use-214C/D Corridor storage	Second Floor	Bathroom C/d 2142	4/2/2012 1:16:14 PM	4/5/2012	ISSUED
Overlook	24015	#10 Fire doors or smoke barrier doors are blocked or obstructed or otherwise inoperable-214:entrance door propped open	Second Floor	Kitchen/living Area 214	4/2/2012 1:19:40 PM	4/5/2012	ISSUED
Overlook	24017	#12 means of egress is obstructed and not readily available for use-103: main entry/corridors & remove propane cylinders	First Floor	Kitchen/living Room 103	4/2/2012 1:23:50 PM	4/5/2012	ISSUED
Overlook	24018	#13 Curtains, draperies, hangings& other decorative materials on ceilings & walls, not flame resistant-109C: Green ceiling tapestry around light	First Floor	Room C 109c	4/2/2012 1:25:46 PM	4/5/2012	ISSUED
Overlook	24025	#16 Candles, Incense, and similar open-producing items shall not be allowed in sleeping units....112B: Candles on L desk	First Floor	Room B 112b	4/3/2012 5:50:05 AM	4/6/2012	ISSUED
Overlook	24026	#17 Candles, incense, and similar open-flame-producing items shall not be allowed in sleeping units, 112C: Candles on L desk	First Floor	Room C 112c	4/3/2012 5:55:06 AM	4/6/2012	ISSUED
Overlook	24255	Change batteries in both gym side emergency panic bars. Did this 4-19-12 need WO	First Floor	Hallway,by 112 - 116	4/20/2012 1:19:00 PM	4/23/2012	ISSUED
Overlook	24260	The emergency push bar was beeping due to a low battery. Officer LaBarre turned it off to prevent further complaints until fixed.	First Floor	Stairs, By 116	4/23/2012 8:24:00 AM	4/26/2012	ISSUED
Overlook	24298	Desk drawer keeps falling apart, student has tightened screws 2x and cant not get it to stay together.	First Floor	Room B 112b	4/26/2012 2:44:26 PM	4/29/2012	ISSUED
Overlook - 11 Total:							

Pickett Hall

--	--	--	--	--	--	--	--

Pickett Hall	492	please fix the broken window-Window has "do not open" in black magic marker on the window. Room is next on teh left after HEOP room HEOP room is Pic 203	Pickett Hall	2nd Floor	3/28/2012 8:55:00 AM	3/31/2012	ISSUED
Pickett Hall - 1 Total:							

Safety Building

Safety Building	24135	Please change our furnace filters.	Safety Building	1st Floor	4/10/2012 12:51:07 PM	4/13/2012	ISSUED
Safety Building	24156	Install drainage around exterior of campus safety building to prevent water seepage into building.	Paul Smiths College	Safety Building	4/12/2012 11:00:13 AM	4/15/2012	ISSUED
Safety Building - 2 Total:							

Saranac Lake Residence Hall

Saranac Lake Residence Hall	24043	#2 LPG fuel cooking device within 10' of combustible construction-rear entrance: grill chained to post uner porch	Saranac Lake Residence Hall	Bldg Ext	4/3/2012 8:34:00 AM	4/6/2012	ISSUED
Saranac Lake Residence Hall	24050	#9 Fire protection system not inspected tested, or maintained per refrence standard-Basemetn sprinkler room: no spare concealed, wrench	Saranac Lake Residence Hall	Basement	4/3/2012 8:55:00 AM	4/12/2012	ISSUED
Saranac Lake Residence Hall	24054	#13 Class III standpipe systems shall have hose connections as required for Class I....FCNYS 905.4 Signange for stairwell without standpipe connection	Paul Smiths College	Saranac Lake Residence Hall	4/3/2012 9:24:47 AM	4/12/2012	ISSUED
Saranac Lake Residence Hall - 3 Total:							

Saratoga Hall

Saratoga Hall	24059	#5 Curtains, draperies, hangings, & other decorative materials on ceilings & walls not flame resistant 119: 2 flags on the ceiling	1st Floor	Students Room 119	4/3/2012 10:31:07 AM	4/6/2012	ISSUED
Saratoga Hall	24062	Required fire resistance rating of walls, shafts, or floors not maintained ...Floor #1 laundry room: door damaged (on hold till new door arrives)	1st Floor	Laundry Room By 113	4/3/2012 10:46:00 AM	4/11/2012	ONHOLD
Saratoga Hall	24056	#2 Swinging fire doors do not close form the full-open position and latch automatically. Floor #2 Across form 204	Saratoga Hall	2nd Floor	4/3/2012 9:55:00 AM	4/12/2012	ISSUED
Saratoga Hall	24058	#4 Required fire resistance rating of walls, shafts, or floors not maintained...Floor #2 laundry room: door damaged (on hold till new door arrives)	2nd Floor	Laundry Room 216	4/3/2012 10:16:00 AM	4/13/2012	ONHOLD
Saratoga Hall	24067	#13 Clothes dryer exhaust systems shall be,...exhausted in accordance with manufacturer's instructions	Paul Smiths College	Saratoga Hall	4/3/2012 11:11:00 AM	4/13/2012	ISSUED
Saratoga Hall	24169	Toilet paper dispenser needed in handicap bathroom.	1st Floor	Restroom By 106	4/13/2012 9:16:00 AM	4/16/2012	ISSUED
Saratoga Hall	24170	Toilet paper dispenser needed in bathroom across from	Basement	Restroom By	4/13/2012	4/16/2012	ISSUED

		classroom 008		010	9:22:00 AM		
Saratoga Hall	24171	Handicap bathroom heater is leaking water; small leak.	2nd Floor	Restroom By 206	4/13/2012 9:33:06 AM	4/16/2012	ISSUED
Saratoga Hall - 8 Total:							

Saunders Complex

Saunders Complex	21770	The tunnel needs to be painted and behind the stairs.-The floor near the armory and court room needs to be painted.	Paul Smiths College	Saunders Complex	10/19/2011	10/24/2011	ONHOLD
Saunders Complex	23591	Reroute the roof drain in the pool stairwell leading out the front of the building. See Tony for details.	Paul Smiths College	Saunders Complex	2/23/2012	2/28/2012	ISSUED
Saunders Complex	24257	Please replace screen hardware for Joey	2nd Floor	Dance Studio	4/20/2012 1:13:39 PM	4/23/2012	ISSUED
Saunders Complex - 3 Total:							

Sewage Treatment Plant

Sewage Treatment Plant	431	Fire extinguisher improperly selected, installed, or maintained. Please see if extinguisher is up to date and replace if necessary.	Paul Smiths College	Sewage Treatment Plant	3/27/2012 5:41:00 AM	3/30/2012	ISSUED
Sewage Treatment Plant	432	Fire extinguisher improperly selected, installed, or maintained.	Paul Smiths College	Sewage Treatment Plant	3/27/2012 5:45:00 AM	3/30/2012	ISSUED
Sewage Treatment Plant - 2 Total:							

Sporck Admissions Center

Sporck Admissions Center	22724	sporck bathrooms on the bottom floor all need touch up paint	Paul Smiths College	Sporck Admissions Center	1/5/2012	1/10/2012	ONHOLD
Sporck Admissions Center	23562	Downstairs kitchen small tile next to stove completely missing white 2" tile.	Ground Floor	Kitchen	2/24/2012	2/29/2012	ISSUED
Sporck Admissions Center	24068	#2 Required fire resistance rating of walls, shafts, or floors not maintained...Fire doors for boiler room/elevator room	Paul Smiths College	Sporck Admissions Center	4/3/2012 11:13:00 AM	4/13/2012	ISSUED
Sporck Admissions Center - 3 Total:							

Upper St Regis

Upper St Regis	312	Someone stole this resident's window screen. Please replace.	1st Floor	Bedroom 112c	3/19/2012 10:25:41 AM	3/22/2012	ISSUED
Upper St Regis	319	Due to unknown reasons screens from hallway windows nearest the A stair well are no longer in place. Request 2 replacements.	Upper St Regis	2nd Floor	3/20/2012 4:55:38 AM	3/22/2012	ISSUED

Upper St Regis	401	#1 Means of egress is obstructed and not readily available for use. Corridor storage	2nd Floor	Bedroom 213d	3/26/2012 8:48:00 AM	3/29/2012	ISSUED
Upper St Regis	405	#5 Multiple candles on right desk	1st Floor	Bedroom 110c	3/26/2012 9:00:00 AM	3/29/2012	ISSUED
Upper St Regis	406	#6 Candle on right desk.	1st Floor	Bedroom 110d	3/26/2012 9:08:00 AM	3/29/2012	ISSUED
Upper St Regis	407	#7 candle on left desk	1st Floor	Bedroom 104c	3/26/2012 9:10:00 AM	3/29/2012	ISSUED
Upper St Regis	410	#10 Inadequate coverage of corridors, auto sensors.	Paul Smiths College	Upper St Regis	3/26/2012 9:35:00 AM	3/29/2012	ISSUED
Upper St Regis	415	Broken window in the classroom, only the outside pane is broken.	Paul Smiths College	Upper St Regis	3/26/2012 10:51:00 AM	3/29/2012	ISSUED
Upper St Regis	419	A window was reported broken in the 2nd floor of Upper St. Regis in the classroom.	2nd Floor	Multi Purpose Room 201	3/26/2012 12:20:00 PM	3/29/2012	ISSUED
Upper St Regis	439	Ceiling damage due to water.	1st Floor	Bedroom 104d	3/27/2012 8:00:51 AM	3/30/2012	ISSUED
Upper St Regis	24224	Odor resident requested that the kitchen sink trap be inspected for clog issues. Foul odor emitting from that region.	2nd Floor	Main Room 207	4/18/2012 10:24:46 AM	4/21/2012	ISSUED
Upper St Regis - 11 Total:							

Visitors Interpretive Center

Visitors Interpretive Center	24069	#1 Open junction boxes and open wiring splices present Boiler room: R of water pump-#2 disconnect cover	1st Floor	Mechanical Room 101aa	4/3/2012 11:20:06 AM	4/13/2012	ISSUED
Visitors Interpretive Center	24073	#5 Fire extinguisher improperly selected, installed, or maintained-Elevator machine room: Last annual 2010-See remarks	1st Floor	Elevator Room 103	4/3/2012 11:32:40 AM	4/13/2012	ISSUED
Visitors Interpretive Center	24077	#9 Repairs, maintenance, alterations, or installations not executed or installed in a workmanlike manner-Auditorium cable run through door and damaged	1st Floor	Theater 110	4/3/2012 11:41:40 AM	4/13/2012	ISSUED
Visitors Interpretive Center	24078	#11 Electrical wiring, devices, etc. modified or damaged or constitutes an electrical shock hazard-Floor #2 library conference room-See remarks	Visitors Interpretive Center	1st Floor	4/3/2012 11:44:09 AM	4/13/2012	ISSUED
Visitors Interpretive Center - 4 Total:							

Walkway And Paths

Walkway And Paths	314	Metal stair treads are coming off cement, cement is all breaking up. Between Upper and Lower	Walkway And Paths	Walkway And Paths	3/19/2012 9:38:00 AM	3/22/2012	ONHOLD
Walkway And	23792	Back of Paolozzi on the lake walk, light pole junction box cover	Walkway And	Walkway And	3/29/2012	4/1/2012	ISSUED

Paths		is off.	Paths	Paths	7:46:41 AM		
Walkway And Paths	24172	on the boardwalk to the froestry cabin there is a green box - maybe communication box-that has wires sticking out and is knocked over.	Paul Smiths College	Walkway And Paths	4/13/2012 1:20:09 PM	4/16/2012	ISSUED
Walkway And Paths - 3 Total:							